


Fairview Industrial Park

Evacuation Zones, Evacuation Routes and Main Assembly Point



Route 1 - Exit via Marsh Way and Main Entrance

Route 2 - Exit via Trek/Function Warehouse and via Creek Way